

## CSC INSPECTION – SUDU756 LOWER SIDE RAIL

|                                  |                   |                            |                           |                             |
|----------------------------------|-------------------|----------------------------|---------------------------|-----------------------------|
| Container Number<br>SUDU 7560048 | Location<br>LKCMB | Survey Date<br>28/AUG/2014 | Survey Company<br>SINSPEC | Surveyor (Print Name)<br>NR |
|----------------------------------|-------------------|----------------------------|---------------------------|-----------------------------|

Manufacture Date 2010/07 This is to certify that an inspection of the lower side rails has been carried out in conformance to HSDG instructions and confirm that the container is fit or (unfit) (circle one) for continued safe service in conformance to CSC.

Doors Right Side Lower Rail Front



Condition Comments – 2<sup>nd</sup> Forklift pocket entry found fissure paint - No action

Yellow Area: Primary

Green Area: Secondary

Front Left Side Lower Rail Doors



Condition Comments - OK

ATTACH PHOTOS HERE



